



ALERT SERVICE BULLETIN

#0001

INSPECTION OF 912 SERIES, ENGINE BRACKET MOUNTS.

ADVISORY

Release Date: 03 August 2023

Effective Date: 03 August 2023

Compliance Time: Before next flight, every pre-flight, next Annual Inspection.

Attention: All pilots and AME/AP's

It has come to our attention,

Owners and operators whose aircraft are fitted with the 912 series Engine bracket are to carry out a thorough inspection for any cracks on the engine bracket and specifically along all welding joints. Pay careful attention for fatigue, corrosion and any form of burn through which may cause a loss of wall thickness on the material resulting in a weaker join along the engine bracket.

If any of the above is found on inspection, **flight is not recommended. Contact Solowings for more information.**